

## Technical Service Bulletin

Bulletin No.	R_03_2021
Date	May 2021

## Vent 28 F

Dear customer,

during the installation of the product Vent 28 F

Item No. 07902-01-Item No. 07902-01B

in order to prevent any water infiltration, remember to seal the underside of the outer frame well for a minimum width of 10 mm, following the appropriate tracks, especially at the points where there are the 2 plastic joints (as shown in the pictures on the right).

Recommended sealant: SIKALASTOMER-710 / THEROSTAT II (or other butyl sealant)

Never remove the plastic joints from their seats.





