

Bulletin No.	R_03_2023
Date	July 2023

Carry-Bike Pro / Pro N

Dear Customer,

Due to a defect in the assembly of the Bike-Block support tube screw,
in order to ensure greater safety, for Carry-Bike Pro and Pro N (codes 02096-09- 02096-09V).

with Serial Number with the following prefixes:

**M-BI3BD / M-BI3DD / M-BI3PD / M-BI3SD / M-BI4DD / M-BI4FD / M-BI4GD /
M-BI4HD / M-BI4SD / M-BI4TD / M-BI54D / M-BI58D / M-BI59D / M-BI5AD /
M-BI5ND / M-BI5PD / M-BI5TD / M-BI63D / M-BI69D / M-BI6CD / M-BI6PD /
M-BI6XD / M-BI76D / M-BI7AD / M-BI7GD**

Please request replacement part free of charge
code 98656M610

