

Bulletin No.	R_03_2025_revC
Date	September 2025

**Kit VW T5 / T6 98655Z156 - Kit Combi Rail Bracket 98655Z147  
for F45s and F43van awnings**

Dear Customer,

we understand a production lot of our awning brackets may have sealing issues due to a non-compliant component. In case of any loose connections between awning and vehicle, we recommend to contact your dealer to obtain a repair kit to solve your issue.

The repair kit will be provided free of charge.

The replacement can be done in the comfort of your home. Should you prefer assistance, we will support your dealer of choice in the replacement.

Please refer to the guide below for a step by step instruction on the solution to this problem.

We apologise for the inconvenience and remain at your service for any further questions.

Thank you

	Item No.	Item No. - Security kit
Kit VW T5 / T6 Multirail Reimo	98655Z156	98673-378
Kit Combi Rail Bracket	98655Z147	

4x



**REMOVE ONE SCREW AT A TIME, SO AS TO AVOID REMOVING THE AWNING**

**Make the modification for both front and rear bracket**

